


901C Hanging Metal Body Form Assembling Guide

(1) BASE 1 pc.
(2) SPRING 1 pc.
(3) INNER POLE 1 pc.
(4) OUTER POLE 1 pc.
(5) METAL FORM 1 pc.
(6) PENDANT 1 pc.
(7) TOPPER 1 pc.





Step 1

Place BASE firmly on the ground.



Step 2

Insert INNER POLE into the BASE.

Make sure to twist the screw tightly After INNER POLE is inserted into the BASE completely.



Make sure to have INNER POLE standing on the end of the foot pedal.



Step 3

Gently slide in the SPRING to the INNER POLE.



When sliding SPRING over INNER POLE, make sure you are stepping down on the foot pedal with the top of INNER POLE aligned.

-



Step 4

Slide OUTER POLE over INNER POLE.



When sliding OUTER POLE over INNER POLE, make sure you are stepping down on the foot pedal with the top of INNER POLE aligned.



Step 5

Twist the PENDANT into the METAL FORM, along with TOPPER.



Step 6

Hang the METAL FORM to the OUTER POLE.

Twist the screw tightly.



Make sure to twist the screw tightly after hanging up the METAL DRESS FORM

Congratulations !!!

Installation Complete.